



November 18, 2019

**RO# 25024**  
**1970 Porsche 911 / VIN # 9110301644 / Mileage 75522**

**PARTS**

1.	6	Flywheel bolts	911-102-171-00	136.62	US \$
2.	9	Pressure plate bolts	900-067-090-02	23.76	US \$
3.	1	Flywheel seal	999-113-057-52	56.80	US \$
4.	2	Swaybar bushings	901-343-782-00	24.80	US \$
5.	7	Swaybar bushings	901-333-793-03	74.00	US \$
6.	2	Batteries	000911	304.40	US \$
7.	1	Oil line	901-107-331-12	217.56	US \$
8.	1	Console panel	993-632-071-10	258.40	US \$
9.	1	Oil & grease		97.00	US \$
10.	1	Miscellaneous		24.11	US \$
<hr/> Subtotal Parts:				1217.45	US \$

**LABOR**

1.	Check car for oil leak	880.00	US \$	
	R+I engine and transmission			
	Replace flywheel seal			
	Replace oil line from engine block to oil tank			
	Replace swaybar bushings			
	Replace 2 batteries			
	Install customer supplied hood lift			
<hr/> Subtotal Labor:			880.00	US \$
<hr/> Subtotal Parts & Labor:			2,097.45	US \$
Sales Tax:			146.82	US \$
<hr/> Total:			2,244.27	US \$



# TLG Porsche Service

13222 Raymer Street  
 N.Hollywood, CA 91605  
 PH: 818-982-7610  
 Customer Name: \_\_\_\_\_  
 Fax: 818-765-2186  
 Terms: \_\_\_\_\_  
 Fleet # \_\_\_\_\_

5905

04/29/14 01:57 pm  
 EPA# CAL000015360  
 BAR# ARD00264722

PASADENA, CA 91105

Phone 2: \_\_\_\_\_

Year: 70 Make: PORSCHE Model: 911 Vin Number: 91103XXXXX License: NONE/CA Mileage: 74734

Quan	Part Number/Description	Ea	Ext Price
1.0	901.110.060.98 MFI Rod Kit	195.00	195.00
6.0	901.108.391.05 Base Gasket	3.01	18.06
6.0	911.110.191.01 Stack Gasket	3.95	23.70
12.0	BRAD PENN 20/50 Motor Oil	7.35	88.20
1.0	OC-61 Oil Filter	12.95	12.95
6.0	GEAR OIL 80W90 GL-5	6.95	41.70
2.0	901.332.297.00 Axle Gasket	3.72	7.44
1.0	999.113.057.52 Flywheel Seal	21.95	21.95
1.0	999.113.185.40 Selector Shaft Seal	12.95	12.95
1.0	901.107.301.12 Oil Line	124.20	124.20
1.0	TRUNION Steel Trunion	19.85	19.85
1.0	911.116.772.11 Clutch Pivot Bolt	56.73	56.73
2.0	BLADE Wiper Blade	12.00	24.00
2.0	PAD Pedal Pad	6.00	12.00
1.0	SHOE Throttl Shoe	22.00	22.00
1.0	BUSHING Rod Bushing	18.00	18.00
		Total Parts:	698.73

Recommendations:

Tire Pressure: LF \_\_\_\_\_ RF \_\_\_\_\_ LR \_\_\_\_\_ RR \_\_\_\_\_

**NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.**

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) \_\_\_\_\_

**OUR COMPANY  
 APPRECIATES YOUR BUSINESS!  
 THANK YOU!**

Payments:  
 1 09/17/14 4129.37 Check 1383 2:28 pm

Total Labor: 2,143.75  
 Total Parts: 698.73  
 Haz Waste: 9.00  
 Sublet Repairs: 1215.00  
 Discount: 0.00  
 Shop Supplies: 0.00  
 Non Taxable: 0.00  
 Tax: 62.89  
**Total Amount: 4129.37**  
**Payment: 4129.37**  
**Bal Due: .00**

Oper	Repair Instructions	Labor Charge
01	General Inspection Complimentary 27-point inspection of vehicle ... * Inspection form attached*	0.00
02	Fuel Injection Client states that car does not run properly; Another shop worked on car and made recommendations (invoice provided) - Diagnose and advise customer of findings ... Diagnosis confirms that throttle bodies are completely worn out and in need of refurbishment ... Remove and install throttle bodies; Adjust fuel injection	980.00
03	Oil Leaks Engine has significant oil leaks from flywheel seal and selector shaft seal - Remove and install motor and transmission; Remove and install trans from back of engine; Remove and install flywheel and clutch; Remove and replace flywheel seal; Remove and replace selector shaft seal in transmission nose cone	980.00
06	Misc.	0.00
07	Hand Throttle R/R Seat R/R Hand Brake Handle Replace throttle Shoe&Guide Bushing	183.75
* Throttle Body Shipping		40.00
* Throttle Body Refurb.		1,175.00

# INVOICE

## PASADENA BRITISH SERVICE

BENTLEY ROLLS-ROYCE JAGUAR  
LANDROVER ASTON MARTIN

(626) 584-1575

INVOICE #1228  
DATE: NOVEMBER 20, 2012

2525 Nina Street • Pasadena • CA • 91107

TO:

Please make check payable to  
Pasadena British Service

MAKE	MODEL	YEAR	VIN#	MILEAGE	LICENSE #	TERMS
Porsche	911	1970		73962	5UBA770	Upon Receipt

QTY	ITEM #	DESCRIPTION	PARTS	SUBLET	LABOR
1x	91142321001	Fit new clutch cable			170.00
		Clutch cable	97.36		
1x	91142321200	Cable trunion	12.00		

*PD 11/30/12*

SUBTOTAL 279.36

SALES TAX 9.57

TOTAL \$288.93

THANK YOU FOR YOUR BUSINESS!

200605004

Order Date 05/02/06 12:42 pm

Started: 05/03/06 09:44 am

BAR #: AK105357
630 Mary Ann Drive
Redondo Beach, Ca 90278
Phone: 310-318-8760 FAX: 310-376-3392



70 PORSCHE 911 S SIL/BLK
Lic: ?/CA Cyl Eng
Vin: 9110301644 06/70
Eq:
Profile:

Quotes
1 05/15/06 12:11pm 647.72
JEFFEREY in person.

1) CHECK ALL ELECTRICAL COMPONENTS

Job01 MAY 1 TECH #129 Labor: \$30 00

ASSISTED WITH SOLVING ELECTRICAL PROBLEM / LIGHT CHECKS

Status: Completed Tech: Unknown

Job02 MAY PARTS Labor: \$0 00

Table with 5 columns: Part Number, Description, Quantity, Unit Price, Total Price. Rows include BLB3329 BULB, H/L 12v, 50w-N and EL3-007 FUSE, 16 AMP RED-N.

Status: Completed Tech: Unknown

Job03 MAY 1 TECH #125 Labor: \$220 00

WORKED ON FIXING BRAKE LIGHT THAT TURNED ON FRONT PARKING LIGHTS, REMOVED LIGHT ISOLATED WIRES AND REPAIRED.

Status: Completed Tech: Unknown

Job04 MAY 2 TECH #125 Labor: \$385 00

FOUND ISSUE IN REAR OF CAR ON RT. LIGHT SWITCH WIRE, DID LIGHT CHECK & FOUND THAT THE FOG LIGHTS DID NOT WORK, NEITHER DID THE WIPERS., FIXED WIPERS WITH A SIMPLE WIRE MOVE ON THE FUSE PANEL. FOG LIGHTS HAD A SHORT TO GROUND WHICH BLEW A FUSE, CHECKED ALL WIRING WHICH WAS FINE. FOUND 2 BAD BULBS & A SHORT TO GROUND. FIXED THE PROBLEMS, CLEANED ALL CONTACTS & REINSTALLED LIGHTS.

Status: Completed Tech: Unknown

Job05 MAY 31 TECH #125 Labor: \$165 00

INSTALLED SEAT BELTS.

Status: In process Tech: Unknown

Job06 MAY 31 TECH #125 Labor: \$11 00

SECURED DOOR POCKET.

Status: In process Tech: Unknown

----->----->----->-----Continued on the next page----->----->----->----->

200605004

Order Date 05/02/06 12:42 pm

Started: 05/03/06 09:44 am

BAR #: AK105357  
630 Mary Ann Drive  
Redondo Beach, Ca 90278  
Phone: 310-318-8760 FAX: 310-376-3392

Job07 MAY 31 TECH #125

Labor: \$110 00

FOUND VACUUM LEAK OF FUEL INJECTORS.

Status: In process Tech: Unknown

I agree to pay reasonable attorney fees if legal action becomes necessary to enforce collection of debt. All warranties on products sold hereby are those made by the manufacturer. Tillack & Co., Ltd. hereby expressly disclaims all warranties, either expressed or implied, including implied warranty of merchantability or fitness for any items on this invoice. Should I Choose to use Visa/Master card or American Express for payment of this invoice, it is understood that I will be responsible for any credit card processing fees.

Work accepted by \_\_\_\_\_ Date \_\_\_\_\_  
Tillack & Co., Ltd. offers service & restoration for the most unique, complex & expensive automobiles made. The business philosophy of this company is to offer the highest standard of work available without compromise. The guidelines of the State of California, Consumer Protection Act covering automotive repair were drafted to cover main stream automotive repair & do not take into consideration the unique characteristics of the automobiles nor the long term nature of the work performed by this company. Therefore there are unique stipulations imposed by Tillack & co., Ltd.

As the owner or authorized agent of the above referenced automobile, I authorize the repair or restoration work detailed above, along with the necessary parts & materials. I also request the examination of any system that may appear to be deficient. I acknowledge the unique hand built nature of my automobile & understand that it is impossible for Tillack & Co., Ltd. to estimate the exact cost of repairs. Therefore I agree that this estimate is an approximation of charges & is not a binding absolute ceiling to the final cost of repairs or restoration.

I acknowledge that the extraordinary value of my vehicle dictates that I maintain full liability & comprehensive insurance coverage while my vehicle is in possession of Tillack & Co., Ltd. I understand that my insurance is the primary coverage & therefore I will not hold Tillack & Co., Ltd. responsible for loss or damage to the vehicle or it's contents, in the case of accident, fire, theft, or any other cause beyond reasonable control. I authorize the employees of Tillack & Co., Ltd. to operate my vehicle for the purposes of testing, inspection or delivery at my sole risk. I acknowledge an expressed mechanics lien on this vehicle to secure payment to Tillack & Co., Ltd. in the full amount due for repairs. I agree to pay reasonable attorney's fees if legal action becomes necessary to enforce the collection of debt. I agree to pay any difference between the total cost of repairs & payments made by my insurance company. Billing will be sent out on the completion of, biweekly or monthly basis dependant on the duration & work load. Billing is due & payable on receipt, absolutely no term applies. Interest, calculated at 10% per year will be charged on an unpaid balance. Storage at \$50.00 per day will be charged, beginning the day after notification

----->----->----->---Continued on the next page--->----->----->----->

**200605004**

Order Date 05/02/06 12:42 pm

Started: 05/03/06 09:44 am

BAR #: AK105357  
630 Mary Ann Drive  
Redondo Beach, Ca 90278  
Phone: 310-318-8760 FAX: 310-376-3392

I take full responsibility for the operation of my high performance or racing car, acknowledging the dangers of operation therein & the potentially lethal consequences.

Owner or agent \_\_\_\_\_ Date \_\_\_\_\_

**Payments to Tillack & Co., Ltd. Cost Summary**

Status: In process Work Order

Labor	921.00
Parts	11.75
Tax	0.97
Total	\$933.72
Payments	647.42
Bal Due	286.30

Payments: \$647.42  
1 06/07/06 647.42 AMEX 134723

Thank you for choosing Tillack & Co., Ltd.





**PORSCHE**

## **Certificate of Authenticity**

The Porsche vehicle with the identification number listed below was manufactured with the following assembly specifications:

**9110301644**

- ◆ *Model Year/Type: 1970 911 S COUPE*  
*Birth Date/Delivery Date: 08/01/1970*  
*Engine Number: 6302248*  
*Transmission Number: Not Recorded*  
*Exterior Paint Color/Code: Silver Metallic / 8080*  
*Interior Material Color/Type: Black – Leatherette*
- ◆ *Optional Equipment:*
  - U.S. Equipment*
  - Comfort Package*
  - Blaupunkt Radio 'Frankfurt'*
  - Tinted Glass*

*Richard S. Ford*

Richard S. Ford, Vice President & COO  
Porsche Cars North America, Inc.