

Porsche Sugar Land

RO# : 204584 | Tag# : 3816

13426 Southwest Fwy Sugar Land TX US 77478
https://www.porschesugarland.com

Check-in: Thu Oct 17, 2024 | 2:21 PM
Ready for Pickup: Thu Oct 31, 2024 | 1:02 PM

Customer
VIJAYARAGHAVAN
IYENGAR
1382
(860) 834 - 3918
Raghavan.reck@gmail.com
5302 Lockwood Bend
Lane
Sugar Land, TX 77479

Vehicle
1998 Porsche Boxster
WPOCA2989WU625030
54,841 Mi In / 54,843 Mi
Out

Service Advisor
Philip Pham
650012
(346) 239 - 5153

1.	01, RECOMMENDATION	Client states conv top doesn't close fully needs adjustment. - see advisor for details Replacement of the broken adjustment arms of the convertible top.	Customer Pay	\$1,772.32
----	--------------------	--	--------------	------------

Job added by Philip Pham on Thu Oct 17, 2024 | 2:21 PM

1.Worn out/broken arms of the convertible top.

01 -RECOMMENDED SERVICE Labor \$0.00

Technician

650017

RECOMMENDATION -RECOMMENDATION Labor \$857.50

Technician

650017

1. Replaced the broken adjustment arms

Parts \$914.82

98656158002 - slide rod 1 SOR

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	1

99992403900 - Bush 2 SOR



Porsche Sugar Land

RO# : 204584 | Tag# : 3816

Customer
1382

Vehicle
WPOCA2989WU625030

Service Advisor
Philip Pham

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	2

98656177900 - Spacer sleeve 2 **SOR**

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	2

90024905409 - Countersunk-head screw 2 **SOR**

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	2

98656187900 - Ball pin 2 **SOR**

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	2

90003400105 - Hexagon nut 2 **SOR**

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	2

98656188100 - Rubber bush 2 **SOR**

SOR No	Requested By	SOR Date	SOR Qty
3308	Philip Pham	28 Oct 2024	2

98656127902 - Push rod 2 **SOR**

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	2

98656157901 - slide rod 1 **SOR**



Porsche Sugar Land

RO# : 204584 | Tag# : 3816

Customer
1382

Vehicle
WPOCA2989WU625030

Service Advisor
Philip Pham

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	1

2. 1YRSTATE 1 YEAR STATE INSPECTION Customer Pay \$25.50

Job added by Philip Pham on Thu Oct 17, 2024 | 2:21 PM

1.1 YEAR STATE INSPECTION

1YRSTATE -1 YEAR STATE INSPECTION Labor \$25.50

Technician

650017

1. PERFORMED 1 YEAR STATE INSPECTION

3. MPVI PERFORM CERTIFIED MULTI-POINT VEHICLE INSPECTION Internal Pay \$0.00

Tags: MPI

Job added by Philip Pham on Thu Oct 17, 2024 | 2:21 PM

1.inspection

MPVI -PERFORM CERTIFIED MULTI-POINT VEHICLE INSPECTION Labor \$0.00

Technician

650017

1. PERFORMED CERTIFIED MULTI POINT VEHICLE INSPECTION. SUBMITTED INSPECTION FORM WITH VEHICLE STATUS.VALUE OF \$123.00 NO CHARGE.

4. RECOMMENDATI Replacement of the horns. Customer Pay \$542.74
ON

Job added by Philip Pham on Mon Oct 21, 2024 | 5:49 PM

1.Low tone horn is inoperative.



Porsche Sugar Land

RO# : 204584 | Tag# : 3816

Customer
1382

Vehicle
WPOCA2989 WU625030

Service Advisor
Philip Pham

RECOMMENDATION -RECOMMENDATION

Labor \$367.50

Technician

650017

1. Replaced the horns

Parts

\$175.24

99663520608 - Fanfare 1 **SOR**

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	1

99663520508 - Fanfare 1 **SOR**

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	1

99661294700 - Adapter cable 2 **SOR**

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	2

5. RECOMMENDATI ON Gas cap replacement

Customer Pay \$184.74

Job added by Philip Pham on Mon Oct 21, 2024 | 5:49 PM

1.The gas cap tether is broken and the seal is cracking

RECOMMENDATION -RECOMMENDATION

Labor \$0.00

Technician

650017

1. Replaced the gas cap

Parts

\$184.74

99720198000 - cap with retaining strap for fuel tank 1 **SOR**



Porsche Sugar Land

RO# : 204584 | Tag# : 3816

Customer
1382

Vehicle
WPOCA2989WU625030

Service Advisor
Philip Pham

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	1

6. TIRE1 Replacement of the left rear tire. Customer Pay \$477.16

Job added by Philip Pham on Mon Oct 21, 2024 | 5:49 PM

1.The left rear tire has a nail in it and is leaking.

TIRE1 -REPLACE ONE TIRE Labor \$127.50

Technician

650017

1. REPLACED ONE TIRE

Parts \$349.66

11435 - 255/40ZR17 Michelin Pilot Sport PS2 N3 1 **SOR**

SOR No	Requested By	SOR Date	SOR Qty
3247	Philip Pham	21 Oct 2024	1

Additional Fees	Sale Amount
SSC - Shop Supply Charges	\$75.00

	Labor	\$1,378.00
	Parts	\$1,624.46
	Sublet Labor	\$0.00
	Sublet Parts	\$0.00
	Fees	\$75.00
	Discounts	\$0.00
	Tax	\$134.01
	Deductible	\$0.00
	Insurance/Warranty	\$0.00
Original Estimate Thu Oct 17, 2024 2:21 PM	\$295.00	
	Invoice Total	\$3,211.47



Porsche Sugar Land

RO# : 204584 | Tag# : 3816

Customer
1382

Vehicle
WPOCA2989 WU625030

Service Advisor
Philip Pham

Next service due: 60000 miles on Fri Apr 25, 2025

SA Notes

Philip Pham approved recommendations on behalf of VIJAYARAGHAVAN IYENGAR.

Mode Of Communication	Previous Estimate	Revised Estimate	Date and Time
Call	\$25.50	\$3,382.57	Mon Oct 21, 2024 at 05:49 PM

Note
auth repairs

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HERE BY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR ACCESSORIES OR REPAIRS PERFORMED TO THE VEHICLE. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR, AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

NOTICE OF WORKERS LIEN PURSUANT TO TEXAS PROPERTY CODE 70.001: The undersigned, being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with S. 9.609 of the Texas Business & Commerce Code until the amount due is paid.



Customer Signature

Date Thu Oct 31, 2024 | 1:28 PM

