

# INVOICE

Brian Donahue  
2540 Lucena St  
Charlotte, NC 28206

brian@changedrivencit.com  
+1 (609) 221-0540  
www.changedrivencit.com



## Bill to

1996 Porsche 993 C4S GR  
WP0AA2998TS322506  
Change Driven( In House)  
2540 Lucena St  
Charlotte, NC 28206 US

## Ship to

Change Driven( In House)  
2540 Lucena St  
Charlotte, NC 28206 US

## Invoice details

Invoice no.: 00271  
Terms: Net 30  
Invoice date: 11/10/2025  
Due date: 12/10/2025

#	Date	Product or service	Description	Qty	Rate	Amount
1.	10/21/2025	Labor	-Perform Engine Leak Down Test  -R/R (12) Spark Plugs  100psi Inlet Pressure:  Cyl 1: 3% Cyl 2: 3% Cyl 3: 3% Cyl 4: 3% Cyl 5: 3% Cyl 6: 2%	3.5	\$140.00	\$490.00
2.	10/22/2025	Labor	-R/R Lower Engine Valve Cover Gaskets, Hardware  - R/R Timing Chain Cover Gaskets, Hardware  Rear Bumper removed, exhaust system, heat shields, lower engine, perform engine reseal. Replace hardware, clean. Run engine. Inspect for leaks/ sweating.	8.5	\$140.00	\$1,190.00
3.	10/24/2025	Labor	Replace Faulty Passenger Side Window Switch	0.3	\$140.00	\$42.00

4.	10/24/2025	Labor	R/R Headlight Lenses with new OEM Lenses ( Hendrick Porsche)	1	\$140.00	\$140.00
5.	10/25/2025	Labor	-R/R Suspension with Koni Special Active Shocks, Eibach M033 Style Springs, Bump Stops, Bellows  -R/R Front Sway Bar Links	9	\$140.00	\$1,260.00
6.	10/16/2025	Labor	- R/R Alternator.  ( The Bosch remanufactured units are NAL. Furthermore, the stators on these units ( whether new or reman from Bosch have proven fail. Carolina Auto Electric runs an upgraded Stator and elec components in their refurbishment process. Following their service, this alternator IS better than if bought new.)	3.5	\$140.00	\$490.00
7.	10/08/2025	SUBLET ( Service)	Michelin PS4S Tires Mount and Balance	4	\$35.00	\$140.00
8.	10/31/2025	Labor	-R/R LF Wheel Bearing	4	\$140.00	\$560.00
9.	10/31/2025	SUBLET ( Service)	Porsche 993 Four Wheel Alignment, Sublet - MP Motorwerks	1	\$180.00	\$180.00
10.	10/10/2025	SUBLET ( Service)	Multi-Stage Paint Correction and Polish.5 Year Ceramic Coating. Sublet- AD Detail Garage, Charlotte, NC	1	\$1,200.00	\$1,200.00
11.	10/23/2025	SUBLET ( Service)	993 "Big Red" Brake Calipers Refreshed.  Old Stone Guards removed and replaced with STEK Paint Protection Film. Sublet, Joe at Paddock Paint Protection, Charlotte NC.	1	\$550.00	\$550.00
12.	10/29/2025	SUBLET ( Service)	Lower Portion of Front Bumper Cover Refinished due to common parking lot/ Driveway scrapes.  Sublet- Aaron at B&B , Fort Mill, SC	1	\$450.00	\$450.00
13.	10/03/2025	PART	Battery	1	\$155.00	\$155.00
14.	11/10/2025	Labor	PCCM Radio Install ( In Process- Est. Completion, 11/11/2025)  Remove existing head unit. Route GPS antenna through rear parcel shelf, mount display panel for Iphone Cord, wire, test.	7	\$140.00	\$980.00
15.	10/20/2025	PART	99917018390 7403 Spark Plug	12	\$9.85	\$118.20

16.	10/27/2025	<b>PART</b>	Porsche 3 Spoke 996 40th Anniv ( Silver Crest) Airbag, Steering Wheel	1	\$550.00	\$550.00
17.	10/27/2025	<b>Labor</b>	Install 996 3 Spoke Wheel, Align on Hub	0.75	\$140.00	\$105.00
18.	10/28/2025	<b>Labor</b>	993 Oil Service	1.5	\$140.00	\$210.00
19.	10/28/2025	<b>Labor</b>	G64 Front Differential Fluid Flush	1	\$140.00	\$140.00
20.	10/28/2025	<b>PART</b>	Motul 'Gear 300' 75/90	1	\$38.75	\$38.75

**Total** **\$8,988.95**

### Ways to pay



[View and pay](#)

# INVOICE

Brian Donahue  
2540 Lucena St  
Charlotte, NC 28206

brian@changedrivencit.com  
+1 (609) 221-0540  
www.changedrivencit.com



## Bill to

1996 Porsche 993 C4S  
WP0AA2998TS322506  
Change Driven( In House)  
2540 Lucena St  
Charlotte, NC 28206 US

## Ship to

Change Driven( In House)  
2540 Lucena St  
Charlotte, NC 28206 US

## Invoice details

Invoice no.: 00270  
Terms: Due on receipt  
Invoice date: 11/10/2025  
Due date: 11/10/2025

#	Date	Product or service	Description	Qty	Rate	Amount
1.	10/16/2025	<b>PART</b>	964-105-902-00  Valve Cover Gasket Set, Hardware	1	\$192.94	\$192.94
2.	10/16/2025	<b>PART</b>	Hood Strut 99351133100	2	\$39.24	\$78.48
3.	10/16/2025	<b>PART</b>	Decklid Strut 911-512-331-02	1	\$37.15	\$37.15
4.	10/16/2025	<b>PART</b>	Chain Cover Gasket Set 100912180	1	\$182.86	\$182.86
5.	10/18/2025	<b>SUBLET ( Service)</b>	Bosch Alternator Rebuild , Sublet Carolina Auto Electric	1	\$576.89	\$576.89
6.	10/18/2025	<b>PART</b>	Headlight Lens 993-631-903-00	1	\$203.56	\$203.56
7.	10/18/2025	<b>PART</b>	Headlight Lens 993-631-904-00	1	\$203.56	\$203.56
8.	10/16/2025	<b>PART</b>	964-613-621-02-01C-M24	1	\$36.50	\$36.50
9.	10/16/2025	<b>PART</b>	993-361-303-03 OEM 993 'C4S' Wheel Cap	4	\$52.82	\$211.28
10.						

	10/16/2025	<b>PART</b>	Stabilizer Link ( Left) 993-343-069-83	1	\$178.35	\$178.35
11.	10/16/2025	<b>PART</b>	Stabilizer Link ( Right) 993-343-070-83	1	\$178.35	\$178.35
12.	10/16/2025	<b>PART</b>	Porsche Classic Radio ( PCCM+)	1	\$1,352.12	\$1,352.12
13.	10/16/2025	<b>PART</b>	Michelin Pilot Sport 4S 285/30/18	2	\$407.99	\$815.98
14.	10/16/2025	<b>PART</b>	Michelin Pilot Sport 4S 225/40/18	2	\$253.99	\$507.98
15.	10/16/2025	<b>PART</b>	999-190-104-30 Blind Rivet	4	\$2.16	\$8.64
16.	10/16/2025	<b>PART</b>	993-505-633-01 Retaining Strip	1	\$78.81	\$78.81
17.	10/16/2025	<b>PART</b>	999-507-441-09 Speed Nut	4	\$2.38	\$9.52
18.	10/16/2025	<b>PART</b>	Brake Fluid	2	\$13.84	\$27.68
19.	10/16/2025	<b>PART</b>	Liqui Moly 5w/40	10	\$9.89	\$98.90
20.	10/16/2025	<b>PART</b>	911 95-98 993-107-203-04 Oil Filter	1	\$38.24	\$38.24
21.	10/16/2025	<b>PART</b>	99310720305 Oil Filter ( Small)	1	\$25.00	\$25.00
22.	10/20/2025	<b>PART</b>	(8745-1252L) Koni Special Active, Left Front	1	\$300.77	\$300.77
23.	10/20/2025	<b>PART</b>	(8745-1252R) Koni Special Active, Right Front	1	\$300.77	\$300.77
24.	10/20/2025	<b>PART</b>	( 8245-1253L) Koni Special Active, Left Rear	1	\$225.58	\$225.58
25.	10/20/2025	<b>PART</b>	( 8245-1253R) Loni Special Active , Right Rear	1	\$225.58	\$225.58
26.	10/20/2025	<b>PART</b>	Bump Rubber 964.343.30	2	\$16.73	\$33.46
27.	10/20/2025	<b>PART</b>	Rear Damper Bellows 993.333.10	2	\$21.78	\$43.56
28.	10/20/2025	<b>PART</b>	Front Damper Bellows 993.343.505.99	1	\$10.89	\$10.89
29.	10/20/2025	<b>PART</b>	99905304104	1	\$58.73	\$58.73

---

Total

**\$6,392.13**

---

### Ways to pay



View and pay