

REPAIR ORDER - AUDIT COPY			Santa Barbara Auto Group 402 S. Hope St. Santa Barbara, CA 93105 Phone: (805) 682-2000		Work Phone	R/O Open Date	R/O Number
SANTA BARBARA AUTO GROUP 402 S. Hope St. Santa Barbara, CA 93105					Home Phone	R/O Close Date	Receipt No.
					Body	Mileage In	Mileage Out
Year	Make	Model	License Number		Service Advisor		
1994	PORSCHE	911 SPEEDSTER			CLARA LUNDY		
Vehicle Identification Number			Color		Account No.	Delivery Date	In-Service Date
WPOCB2960RS465258			GRAND PRIX				


INVENTORY: U10209

#1 - SAFETY: USED CAR/PRE-PURCHASE SAFETY INSPECTION Caused by Safety inspection. Work performed by Tech 111 2.00hrs @ 175.00 350.00 Performed safety inspection per Porsche instructions. All systems working as designed.	I
#2 - SMOG: CLIENT REQUESTS SMOG INSPECTION/CERTIFICATION FOR STATE REGISTRATION PURPOSES. NOTE BY LAW, YOU MAY CHOOSE ANOTHER LICENSED SMOG CHECK FACILITY TO PERFORM ANY NEEDED REPAIRS/ADJUSTMENTS THAT THE SMOG Caused by PERFORM SMOG INSPECTION. Work performed by Tech 707* 0.80hrs 88.00 PERFORMED AND PASSED CALIFORNIA STATE SMOG INSPECTION.	I
#3 - MISC: MISCELLANEOUS SALES REQUESTS LEAK DOWN (COMPRESSION TEST) BE PERFORMED. PLEASE NOTE EACH RESULT. Caused by Compression test. Work performed by Tech 111 4.00hrs @ 175.00 700.00 Performed compression test per sales request. Cylinder 1 -180psi Cylinder 2 -181psi Cylinder 3 -181psi Cylinder 4 -182psi Cylinder 5 -181psi Cylinder 6 -180psi	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	1138.00				
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1138.00				

Porsche all Speedster - White

Vin: WP0CB2A60RS465258



B6 (Mezger & MA1)
911 914/6 964 993
Water Cooled Turbo
GT1 GT2 GT3 GT4
9x7.2 991 992

type engine
for engine



Smog Check Vehicle Inspection Report (VIR)



www.esp-global.com

www.autorepair.ca.gov

Test Date/Time: 11/15/2024@08:18:28

Model Year:	1994	Make:	PORSCHE	Model:	911 CARRERA 2
License:	NONE	State:	XX	VIN:	WPOCB2960RS465258
Engine Size:	3.60 L	Type:	Passenger Car	Transmission:	Manual
GVWR:	N/A	Test Weight:	N/A	Cylinders:	6
Odometer:	16,897	Certification:	California	VLT Record #:	25905
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	Initial Registration

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: SK611640

DMV ID Number: 5691K728S588

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Not applicable	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Non Adjustable	Ignition Timing: N 00	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Pass	Fuel Evaporative Controls Functional		

Idle Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
Idle	883	15.2	0.3	100	17	0	1.00	0.00	0.00	Pass
2500 RPM	2627	15.5	0.1	130	12	0	1.00	0.10	0.00	Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information


SANTA BARBARA AUTO GROUP
402 S. HOPE AVE. SANTA BARBARA CA. 93105
805-682-2000
Station Number: RC233549

Technician Name/Number: URIBE, ANDREW/EO634294
Repair Tech Name/Number:
Software Version/EIS Number: 2402 / EP525798

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

11/15/24
Date

Technician's Signature



This report provided free of charge by:
Santa Barbara Auto Group
 402 S Hope Ave
 Santa Barbara, CA 93105
 (805) 682-2000

4.7 / 5.0

67 Verified Reviews









Vehicle History Report™

US \$44.99

1994 PORSCHE 911 CARRERA 2

VIN: WP0CB2960RS465258
 CONVERTIBLE
 3.6L H6 F
 GASOLINE
 REAR WHEEL DRIVE

- No accidents or damage reported to CARFAX
-  5 Service history records
-  2 Previous owners
-  Personal vehicle
-  Last owned in California
-  **16,520** Last reported odometer reading



This CARFAX Report Provided by:
Santa Barbara Auto Group
 4.7 / 5.0 67 Verified Reviews

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/31/24 at 3:59:26 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported

	Warranty Expired	Warranty Expired
Basic Warranty Original warranty estimated to have expired.		

CARFAX Title History

	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	No Problem	No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	No Problem	No Problem

CARFAX Ownership History

The number of owners is estimated

	Owner 1	Owner 2
Year purchased	1994	2021
Type of owner	Personal	Personal
Estimated length of ownership	27 yrs. 6 mo.	3 years
Owned in the following states/provinces	Arizona, Utah	California
Estimated miles driven per year	—	—

BUYERS GUIDE

IMPORTANT: Spoken promises are difficult to enforce. Ask the dealer to put all promises in writing. Keep this form.

Porsche

911 Speedster 1994

WPOCB2960RS465258

VEHICLE MAKE

MODEL

YEAR

VEHICLE IDENTIFICATION NUMBER (VIN)

WARRANTIES FOR THIS VEHICLE:



AS IS - NO DEALER WARRANTY

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE.



DEALER WARRANTY

- FULL WARRANTY.
- LIMITED WARRANTY. The dealer will pay ____% of the labor and ____% of the parts for the covered systems that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions, and the dealer's repair obligations. *Implied warranties* under your state's laws may give you additional rights.

SYSTEMS COVERED:

DURATION:

_____	_____
_____	_____
_____	_____
_____	_____

NON-DEALER WARRANTIES FOR THIS VEHICLE:

- MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired on some components of the vehicle.
- MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.
- OTHER USED VEHICLE WARRANTY APPLIES.

Ask the dealer for a copy of the warranty document and an explanation of warranty coverage, exclusions, and repair obligations.

- SERVICE CONTRACT. A service contract on this vehicle is available for an extra charge. Ask for details about coverage, deductible, price, and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, *implied warranties* under your state's laws may give you additional rights.

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtain a vehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safecar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of the resources on these sites.

SEE OTHER SIDE for important additional information, including a list of major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en español, pídale una copia de la Guía del Comprador en español.