



# Report

## 1983 Porsche 911 SC

170,186 mi | VIN: WP0EA0914DS160973 |

Convertible | 3.0L H6 F | Gasoline | Rear wheel drive



**NO ACCIDENTS REPORTED**

No Accidents or Damage Reported to CARFAX

15 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/27/26 at 9:01:47 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

<b>CARFAX</b> Additional History Not all accidents / issues are reported to CARFAX	Summary
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported

<b>CARFAX</b> Title History	Summary
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	No Problem

<b>CARFAX</b> Detailed History			
Date	Mileage	Source	Comments
05/17/1991	87,769	California Inspection Station Yorba Linda, CA	Passed emissions inspection

05/14/1993	119,184	California Inspection Station Yorba Linda, CA	<b>Passed emissions inspection</b>
04/13/1994	133,407	California Inspection Station Yorba Linda, CA	<b>Passed emissions inspection</b>
03/22/1995	143,948	California Inspection Station Yorba Linda, CA	<b>Passed emissions inspection</b>
01/28/1997	162,768	California Inspection Station Yorba Linda, CA	<b>Passed emissions inspection</b>
04/29/1999	168,472	California Inspection Station Huntington Beach, CA	<b>Passed emissions inspection</b>
02/27/2000		California Motor Vehicle Dept. Corona del Mar, CA	<b>Title issued or updated</b>
07/25/2001		California Inspection Station	<b>Passed emissions inspection</b>
12/24/2003	168,473	California Inspection Station	<b>Passed emissions inspection</b>
07/11/2005	169,658	California Inspection Station	<b>Passed emissions inspection</b>
06/16/2008	170,174	California Inspection Station	<b>Failed emissions inspection</b> <b>- Designated GROSS POLLUTER</b>
07/07/2008	170,177	California Inspection Station	<b>Failed emissions inspection</b>
07/07/2008	170,178	California Inspection Station	<b>Passed emissions inspection</b>
07/01/2016	170,186	California Inspection Station Fullerton, CA	<b>Passed emissions inspection</b>
05/21/2017		Vehicle Exporter	<b>Vehicle exported from</b> - Houston, TX and imported to - The Netherlands

Hmm, we haven't received any information on this car since May 2017. Before you buy, ask the seller for recent service or repair records.

Have Questions? Please visit our Help Center at [support.carfax.eu](http://support.carfax.eu).

## Glossary

### Failed Emissions Inspection




The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

### Gross Polluter

A Gross Polluter is a vehicle that fails an emissions inspection with below-standard scores. These vehicles can pollute as much as 18 times more than a vehicle that passes an emissions inspection. It is illegal to drive or sell a gross polluting vehicle in California, and it cannot be registered with the DMV. CARFAX recommends checking the latest Vehicle Inspection Report to confirm the proper repairs have been completed before purchasing.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  [facebook.com/CARFAX](https://facebook.com/CARFAX)  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

