

REPAIR ORDER - AUDIT COPY Santa Barbara Auto Group 402 S. Hope St. Santa Barbara, CA 93105 Phone: (805) 682-2000			Work Phone	R/O Open Date	R/O Number
				8/03/26	6179472/1
			Home Phone	R/O Close Date	Receipt No.
				8/12/26	Original
SANTA BARBARA AUTO GROUP 402 S. Hope St. Santa Barbara, CA 93105			Body	Mileage In	Mileage Out
			2DR CARRERA C	44648	44650
Year	Make	Model	License Number	Service Advisor	
1996	PORSCHE	911 CARRERA		SARAH GREENE	
Vehicle Identification Number			Account No.	Delivery Date	In-Service Date
WP0CA2995TS340292					
Color					
SILVER					

INVENTORY: U10814C

#2 - A502: CAMPAIGN A-502
 Caused by A502
 Corrected by A502: CAMPAIGN A-502 A502 LRATE:274.00
 Work performed by Tech 111 0.70hrs @ 274.00 191.80
 911624055CX : ELECTRIC MOTOR 1@1628.13 1628.13
 911624055CU : ELECTRIC MOTOR 1@835.33 835.33
 911624055CU : ELECTRIC MOTOR -J@835.33 -835.33
 911624056CX : ELECTRIC MOTOR 1@1628.13 1628.13
 911624056CU : ELECTRIC MOTOR 1@835.33 835.33
 911624056CU : ELECTRIC MOTOR -J@835.33 -835.33
 Performed A502 per Porsche instructions. Removed
 and replaced convertible top locking motor.
 Measured pegs and found them to be at 39mm. Scope
 1. 70tu.

W

#3 * SAFETY: USED CAR/PRE-PURCHASE SAFETY INSPECTION
 ADDED OPERATION
 Caused by Safety inspection.
 Work performed by Tech 111 2.00hrs @ 175.00 350.00
 Performed safety inspection per check list.
 Vehicle passed safety inspection.

I

#4 * ENG: ENGINE MINOR REPAIR PER INTERNAL AUTHORIZATION
 FORM, COMPLETE COMPRESSION TEST.
 ADDED OPERATION
 Caused by Compression test.
 Work performed by Tech 111 4.00hrs @ 175.00 700.00
 Performed compression test per Porsche
 instructions.

I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	1050.00		191.80		
PARTS			3256.26		
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1050.00		3448.06		

Multi-Point Vehicle Safety Inspection

Engine Compartment

1	Oils, Condition, Leak (Engine, Transmission, Transfer Case, Front/Rear Axle)
2	Oils, Other (Level Control P/S, ADS, ASR, ABC, ADS, 4-Matic etc.)
3	Condition of Radiator/Coolant/Hoses
4	Condition of Drive Belts
5	Power Steering Fluid
6	Condition of air filters
7	Throttle Linkage
8	Engine Mounts
9	Condition of A/C, Refrigerant Charge Heater Box Drains
10	Brake Fluid
11	Condition of Battery/Cables, Midtronic Printout
12	Washer Fluid, Condition and Level

OK	Future Attn.	Immed. Attn.

Undercarriage/Drive Train

13	Tire Wear and Pressure (Including Spare)
	Indicate Tread Depth:
	LF 3mm RF 3mm Spare
	LR 3mm RR 3mm
14	Alignment
15	Brake Rotor and Pad Visual Inspection F: 5mm R: 3mm
16	Brake Lines
17	Parking Brake Cables
18	Drive Shaft, Flex Discs and Center Support Bearings
19	Condition of Struts, Shocks
20	Suspension Inspection Ball Joint, Tie Rod Ends Steering Play, Damper, Level Control, ABC
21	Exhaust System, Mufflers, Hanger etc.

OK	Future Attn.	Immed. Attn.

Electrical Systems and Function Test

22	Wiper/Washer Systems Windshield/Rear/Headlamps
23	Headlamps Low/High and All Exterior Lights and Adjustment
24	Tail Lamps/Stop/Turn Signals
25	Horn(s)
26	All Interior Lighting Cigarette Lighter
27	Seat and Steering Column Adjustment/Memory/Heating
28	Power mirrors' Condition/Function/Memory
29	Instrument Cluster, Illumination, MIL Check, Proper Function
30	Radio/All Audio System Function

OK	Future Attn.	Immed. Attn.

Chassis/Body

31	Body Structure Inspection
32	Power windows, Sun Shade Function
33	Interior Trim Fit and Finish Dash, Door Panels, Seats, Wood etc
34	Seat Belts Condition, Function
35	Roll Bar Condition/Function
36	Doors/Trunk/Tailgate operation/Closing Assist
37	Sliding Roof Function Drains

OK	Future Attn.	Immed. Attn.

Disclaimer: Any equipment, component or system that breaks or malfunctions during the inspection is the responsibility of the owner of the vehicle, NOT SANTA BARBARA AUTO GROUP.

Comments/Other:

NA

Customer Signature:

Date:

Service Advisor:

Date:

White Copy: Customer

Yellow Copy: Service Representative

Pink Copy: Vehicle File

